UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,038,505 B2

APPLICATION NO. : 10/750558

DATED

: May 2, 2006

INVENTOR(S)

: Cole et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Figure 1

[Ref no.] 24 "...PULSE CLCOK..." should read --...PULSE CLOCK...--

Column 3

Line 17, "...earlier, 16 latch banks 26..." should read --...earlier, 16 [no bold] latch banks 26...--.

Line 45, "...via 16 corresponding..." should read --...via 16 [no bold] corresponding...--.

Column 5

Line 32, "...a glitch design may..." should read --...a glitch design 168 may...-.

Line 63, "...StbP 204 and StbN 206..." should read --...StbP214 and StbN 216...-.

Signed and Sealed this

Page 1 of 1

Thirty-first Day of July, 2007

JON W. DUDAS Director of the United States Patent and Trademark Office